11/20/24

| BORDEAUX 2 UNIT NUMBERS | NOTICE OF COMMENCE MENT | PERMITS | DEMO'D | CLEANED AFTER DEMO | DRIED | PLUMBING PRE-DRYWALL | ELEC - PRE DRYWALL | INSULA- TION | DRYWALL STOCKED | AIR HANDLER PULLED |
|----------------------------|-------------------------------|---------|----------|--------------------------|----------|-------------------------|-----------------------|-----------------|---|-----------------------|
| G 101 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| G 102 | POSTED 11/20 | | WILL | BE | READY | 11/21/2024 | | | | |
| G 103 | POSTED 11/20 | | WORKING | WORKING | WORKING | COMPLETE | | | | |
| G 104 | Need HO sign & notary | | NO | DAMAGE | * | | | | | |
| G 204 | HOA EXTRAS | | SEE | NOTES | AT | воттом | | | | |
| H 101 | POSTED 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| H102 | POSTED 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | Marcan Superior Andrews Product Policy Street Control | |
| H 103 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| H 203 | HOA EXTRAS | | WIND | DAMAGE | COMPLETE | COMPLETE | EXTRA TO OWNER | COMPLETE | COMPLETE | |
| l 101 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |

| BORDEAUX 2 UNIT NUMBERS | NOTICE OF COMMENCE MENT | PERMITS | DEMO'D | CLEANED AFTER DEMO | DRIED | PLUMBING PRE-DRYWALL | ELEC - PRE DRYWALL | INSULA- TION | DRYWALL STOCKED | AIR HANDLER PULLED |
|----------------------------|-------------------------------|---------|-------------|--------------------------|----------|-------------------------|-----------------------|-----------------|--------------------|-----------------------|
| 1102 | POSTED 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| 1103 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| J 101 | Need HO sign & notary | | START 11/19 | | | | | | | |
| J 102 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | ~ | | | |
| J 103 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| J 104 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| J 105 | POSTED 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K 101 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K 102 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K 103 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |

| BORDEAUX 2 UNIT NUMBERS | NOTICE OF COMMENCE MENT | PERMITS | DEMO'D | CLEANED AFTER DEMO | DRIED | PLUMBING PRE-DRYWALL | ELEC - PRE DRYWALL | INSULA- TION | DRYWALL STOCKED | AIR HANDLER PULLED |
|----------------------------|-------------------------------|---------|----------|--------------------------|----------|-------------------------|-----------------------|-----------------|--------------------|-----------------------|
| K104 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K 105 | RECV'D 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K 106 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K107 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| K 203 | HOA EXTRAS | | WIND | DAMAGE | COMPLETE | N/A | | | | |
| L 101 | POSTED 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| L 102 | Need HO sign & notary | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| L 103 | POSTED 11/20 | | COMPLETE | COMPLETE | COMPLETE | COMPLETE | | | | |
| L 104 | | | OWNER | DOING | | | | | | |

BORDEAUX 2 UPDATE 11/20/24

NOTES

11/19/24

- 1. Large tree behind building G has been removed is complete.
- 2. G204 Drying company was called to moisture ready water intrusion at all windows. Hall Bath and both bedroom windows were dry. The dining room window was wet and recommended it to be removed. The removal of drywall up to four foot was done. Drying and quote to build back will be forthcoming. Hall bath was very wet. It appears water entered through the gable louver. Demo of vanity, drywall at the vanity and part of the wall at commode room. Pictures and quote to build back will follow.
- 3. H203 Water came in through the Gable louver. Louver was removed and stucco'd.